



CMC STEEL TEXAS  
1 STEEL MILL DRIVE  
SEGUIN TX 78155-7510

**CERTIFIED MILL TEST REPORT**  
For additional copies call  
800-227-6489

We hereby certify that the test results presented here  
are accurate and conform to the reported grade specification

Rolando A Davila

Quality Assurance Manager

**1SERIES-BPS®**

HEAT NO.:1080573 SECTION: CHANNEL 5"x6.7# 20"0" A36/572T1 GRADE: ASTM A36-19/A572-18 Gr 50 Tp1 ROLL DATE: 07/18/2022 MELT DATE: 06/11/2022 Cert. No.: 85109541 / 080573A168	S O L D T O	Superior Supply & Steel Co 318 N Cities Service Hwy Sulphur LA US 70663-5424 3376252300 3376258509	S H I P T O	Superior Supply & Steel 318 City Service Highway Sulphur LA US 70663-0000 3376252300 3376258509	Delivery#: 85109541 BOL#: 74891009 CUST PO#: P0233866-11 CUST P/N: DLVRY LBS / HEAT: 4824.000 LB DLVRY PCS / HEAT: 36 EA
---	----------------------------	---	----------------------------	--	---

Characteristic	Value	Characteristic	Value	Characteristic	Value
C	0.13%	Yield to tensile ratio test1	0.77		
Mn	0.73%	Yield Strength test 2	57.2ksi		
P	0.014%	Tensile Strength test 2	74.7ksi		
S	0.022%	Elongation test 2	24%		
Si	0.15%	Elongation Gage Lgth test 2	8IN		
Cu	0.39%	Yield to tensile ratio test2	0.77		
Cr	0.17%				
Ni	0.12%				
Mo	0.031%				
V	0.004%				
Cb	0.011%				
Sn	0.012%				
B	0.0002%				
Ti	0.001%				
N	0.0078%				
Carbon Eq A6	0.32%				
Yield Strength test 1	57.3ksi				
Tensile Strength test 1	74.5ksi				
Elongation test 1	25%				
Elongation Gage Lgth test 1	8IN				
					<p><b>The Following is true of the material represented by this MTR:</b></p> <p>*Material is fully killed and is Hot Rolled Steel</p> <p>*100% melted, rolled, and manufactured in the USA</p> <p>*EN10204:2004 3.1 compliant</p> <p>*Contains no weld repair</p> <p>*Contains no Mercury contamination</p> <p>*Manufactured in accordance with the latest version of the plant quality manual</p> <p>*Meets the "Buy America" requirements of 23 CFR635.410, 49 CFR 661</p> <p>*Warning: This product can expose you to chemicals which are known to the State of California to cause cancer, birth defects or other reproductive harm. For more information go to <a href="http://www.P65Warnings.ca.gov">www.P65Warnings.ca.gov</a></p>

REMARKS :