



CMC STEEL TEXAS  
1 STEEL MILL DRIVE  
SEGUN TX 78155-7510

CERTIFIED MILL TEST REPORT  
For additional copies call  
800-227-6489

We hereby certify that the test results presented here  
are accurate and conform to the reported grade specification

*Drew M. Flecker*  
Drew M. Flecker

1 SERIES-BPS<sup>®</sup>

Quality Assurance Manager

HEAT NO.: 1087695  
SECTION: CHANNEL 6" x 8.2# 20'0"  
A36/57211  
GRADE: ASTM A36-19/A572-21e1 Gr50 Tp1  
ROLL DATE: 08/15/2023  
MELT DATE: 07/21/2023  
Cert. No.: 85529501 / 087695A829

S Superior Supply & Steel Co  
L 318 N CITIES SERVICE HWY  
D SULPHUR LA  
US 70663-5424  
T 3376252300  
O 3376258509

S Superior Supply & Steel Co  
H 318 N CITIES SERVICE HWY  
I SULPHUR LA  
P US 70663-5424  
T 3376252300  
O 3376258509

Delivery#: 85529501  
BOL#: 75533854  
CUST PO#: P0243718-01  
CUST P/N:  
DLVRY LBS / HEAT: 5412.000 LB  
DLVRY PCS / HEAT: 33 EA

Characteristic	Value	Characteristic	Value	Characteristic	Value
C	0.11%	Elongation Gage Lgth test 1	8IN		
Mn	0.87%	Yield to tensile ratio test1	0.75		
P	0.011%	Yield Strength test 2	55.9ksi		
S	0.021%	Tensile Strength test 2	73.0ksi		
Si	0.14%	Elongation test 2	25%		
Cu	0.33%	Elongation Gage Lgth test 2	8IN		
Cr	0.16%	Yield to tensile ratio test2	0.77		
Ni	0.14%				
Mo	0.039%				
V	0.004%				
Cb	0.009%				
Sn	0.012%				
B	0.0003%				
Ti	0.001%				
N	0.0087%				
Carbon Eq A6	0.32%				
Yield Strength test 1	54.6ksi				
Tensile Strength test 1	72.9ksi				
Elongation test 1	25%				

The Following is true of the material represented by this MTR:  
 \*Material is fully killed and is Hot Rolled Steel  
 \*100% melted, rolled, and manufactured in the USA  
 \*EN10204:2004 3.1 compliant  
 \*Contains no weld repair  
 \*Contains no Mercury contamination  
 \*Manufactured in accordance with the latest version of the plant quality manual  
 \*Meets the "Buy America" requirements of 23 CFR635.410, 49 CFR 661  
 \*Warning: This product can expose you to chemicals which are known to the State of California to cause cancer, birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov

REMARKS :