



CMC STEEL TEXAS
1 STEEL MILL DRIVE
SEGUIN TX 78155-7510

CERTIFIED MILL TEST REPORT
For additional copies call
800-227-6489

We hereby certify that the test results presented here
are accurate and conform to the reported grade specification

Rolando A Davila

Quality Assurance Manager

1SERIES-BPS[®]

HEAT NO.:1080520 SECTION: CHANNEL 6"x10.5# 20'0" A36/572T1 GRADE: ASTM A36-19/A572-18 Gr 50 Tp1 ROLL DATE: 09/26/2022 MELT DATE: 06/09/2022 Cert. No.: 85176676 / 080520A824	S O L D T O	Superior Supply & Steel Co 318 N Cities Service Hwy Sulphur LA US 70663-5424 3376252300 3376258509	S H I P T O	Superior Steel 217 Darnall Rd New Iberia LA US 70560-0781 8002529017	Delivery#: 85176676 BOL#: 74992208 CUST PO#: 235954-11 CUST P/N: DLVRY LBS / HEAT: 5040.000 LB DLVRY PCS / HEAT: 24 EA
--	----------------------------	---	----------------------------	--	---

Characteristic	Value	Characteristic	Value	Characteristic	Value
C	0.10%	Yield to tensile ratio test1	0.74		
Mn	0.96%	Yield Strength test 2	54.0ksi		
P	0.017%	Tensile Strength test 2	74.1ksi		
S	0.028%	Elongation test 2	26%		
Si	0.18%	Elongation Gage Lgth test 2	8IN		
Cu	0.39%	Yield to tensile ratio test2	0.73		
Cr	0.20%				
Ni	0.13%				
Mo	0.031%				
V	0.006%				
Cb	0.011%				
Sn	0.011%				
B	0.0003%				
Ti	0.001%				
N	0.0077%				
Carbon Eq A6	0.34%				
Yield Strength test 1	54.6ksi				
Tensile Strength test 1	74.2ksi				
Elongation test 1	27%				
Elongation Gage Lgth test 1	8IN				
					<p>The Following is true of the material represented by this MTR:</p> <p>*Material is fully killed and is Hot Rolled Steel</p> <p>*100% melted, rolled, and manufactured in the USA</p> <p>*EN10204:2004 3.1 compliant</p> <p>*Contains no weld repair</p> <p>*Contains no Mercury contamination</p> <p>*Manufactured in accordance with the latest version of the plant quality manual</p> <p>*Meets the "Buy America" requirements of 23 CFR635.410, 49 CFR 661</p> <p>*Warning: This product can expose you to chemicals which are known to the State of California to cause cancer, birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov</p>

REMARKS :