



SPS Coil Processing Tulsa
 5275 Bird Creek Ave.
 Port of Catoosa, OK 74015

METALLURGICAL TEST REPORT

PAGE 1 of 1
 DATE 05/02/2023
 TIME 00:55:04

S
O
L
D

T
O

S
H
I
P

T
O

13713
 Warehouse 0020
 1050 Fort Gibson Rd
 Catoosa OK 74015-3033

Order	Material No.	Description	Quantity	Weight	Customer Part	Customer PO	Ship Date
40402979-0020	7525060240	1/4 60 X 240 A786 FLOOR PLATE	7	7,882			04/29/2023

Chemical Analysis

Heat No.	B304938	Vendor	STEEL DYNAMICS COLUMBUS DOMESTIC										Mill	STEEL DYNAMICS COLUMBUS				Melted and Manufactured in the USA		
Carbon	Manganese	Phosphorus	Sulphur	Silicon	Nickel	Chromium	Molybdenum	Boron	Copper	Aluminum	Titanium	Vanadium	Columbium	Nitrogen	Tin					
0.0500	0.3300	0.0090	0.0040	0.0200	0.0400	0.0500	0.0100	0.0001	0.1100	0.0260	0.0010	0.0000	0.0000	0.0030	0.0040					

Mechanical / Physical Properties

Mill Coil No. 23B722138										
Tensile (PSI)	Yield (PSI)	% Elong (2 in)	Rckwl	Grain	Charpy	Charpy Dr	Charpy Sz	Temperature	Olsen	
Batch 1001290790	7 EA	7,882 LB		Batch 1001290791	6 EA	6,756 LB				

THE CHEMICAL, PHYSICAL, OR MECHANICAL TESTS REPORTED ABOVE ACCURATELY REFLECT INFORMATION AS CONTAINED IN THE RECORDS OF THE CORPORATION.

The material is in compliance with EN 10204 Section 4.1 Inspection Certificate Type 3.1

This test report shall not be reproduced, except in full, without the written approval of Steel & Pipe Supply Company, Inc.