

STEEL AND PIPE SUPPLY
 SPS Coil Processing Houston
 8500 Clinton Drive
 Port of Houston Gate 1 Road
 Houston, TX 77029

METALLURGICAL TEST REPORT

PAGE 1 of 1
 DATE 03/24/2023
 TIME 14:18:16

S
O
L
D
T
O

S
H
I
P
T
O
17238
 Longview Warehouse
 4750 West Marshall Ave
 Longview TX 75604-4817

Order	Material No.	Description	Quantity	Weight	Customer Part	Customer PO	Ship Date
40400600-0020	70124896	3/8 48 X 96 A36 STP MIL PLT	10	4,902.400			03/22/2023

Chemical Analysis

Heat No.	Vendor	DOMESTIC	Mill	Melted and Manufactured in the USA											
B2221510	STEEL DYNAMICS SOUTHWEST, LLC		STEEL DYNAMICS SOUTHWEST, LLC	Produced from Coil											
Carbon	Manganese	Phosphorus	Sulphur	Silicon	Nickel	Chromium	Molybdenum	Boron	Copper	Aluminum	Titanium	Vanadium	Columbium	Nitrogen	Tin
0.0600	0.8900	0.0100	0.0040	0.0200	0.0400	0.0600	0.0100	0.0000	0.1000	0.0250	0.0010	0.0050	0.0020	0.0090	0.0040

Mechanical / Physical Properties

Mill Coil No.	Tensile (PSI)	Yield (PSI)	% Elong (2 in)	Rckwl	Grain	Charpy	Charpy Dr	Charpy Sz	Temperature	Olsen
22B129874	63400.000	48800.000	32.00			0	NA			
	65500.000	49900.000	37.50			0	NA			
	64500.000	48600.000	36.00			0	NA			

Batch 1001223600 10 EA 4,902.400 LB
 Batch 1001223604 10 EA 4,902.400 LB

Batch 1001223601 10 EA 4,902.400 LB
 Batch 1001223605 2 EA 980.480 LB

Batch 1001223602 10 EA 4,902.400 LB

THE CHEMICAL, PHYSICAL, OR MECHANICAL TESTS REPORTED ABOVE ACCURATELY REFLECT INFORMATION AS CONTAINED IN THE RECORDS OF THE CORPORATION.
 The material is in compliance with EN 10204 Section 4.1 Inspection Certificate Type 3.1
 This test report shall not be reproduced, except in full, without the written approval of Steel & Pipe Supply Company, Inc.