

STEEL AND PIPE SUPPLY
 SPS Coil Processing Houston
 8500 Clinton Drive
 Port of Houston Gate 1 Road
 Houston, TX 77029

METALLURGICAL TEST REPORT

PAGE 1 of 1
 DATE 01/10/2024
 TIME 11:27:12

S
O
L
D

S
H
I
P

17238
 Longview Warehouse
 4750 West Marshall Ave
 Longview TX 75604-4817

Order	Material No.	Description	Quantity	Weight	Customer Part	Customer PO	Ship Date
40414720-0030	70848240	1/4 48 X 240 A36 STP MIL PLT	4	3,267.200			01/10/2024

Chemical Analysis

Heat No.	Vendor	DOMESTIC	Mill	Melted and Manufactured in the USA											
CA8610	NUCOR STEEL GALLATIN		NUCOR STEEL GALLATIN	Produced from Coil Country of Origin: USA											
Carbon	Manganese	Phosphorus	Sulphur	Silicon	Nickel	Chromium	Molybdenum	Boron	Copper	Aluminum	Titanium	Vanadium	Columbium	Nitrogen	Tin
0.2000	0.4600	0.0100	0.0020	0.0400	0.0400	0.0600	0.0200	0.0002	0.1100	0.0360	0.0010	0.0020	0.0000	0.0078	0.0040

Mechanical / Physical Properties

Mill Coil No.	Tensile (PSI)	Yield (PSI)	% Elong (2 In)	Rckwl	Grain	Charpy	Charpy Dr	Charpy Sz	Temperature	Olsen
1819093	73300	48600	32.0			0	NA			
	67900	47900	28.0			0	NA			
	63000	43800	32.0			0	NA			

Batch 1001612283 4 EA 3,267.200 LB

THE CHEMICAL, PHYSICAL, OR MECHANICAL TESTS REPORTED ABOVE ACCURATELY REFLECT INFORMATION AS CONTAINED IN THE RECORDS OF THE CORPORATION.

The material is in compliance with EN 10204 Section 4.1 Inspection Certificate Type 3.1

This test report shall not be reproduced, except in full, without the written approval of Steel & Pipe Supply Company, Inc.